

RESTORED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

One quarter corner common to Sections 25 and 26, T3N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, October 10, 1891.

17"x8"x6" stone 11" in ground with 1/4 on west face; missing.

20" Hemlock bears S80E 32 lks.; now badly rotted root crown, in place.

6" Hemlock bears N60W 41 lks.; now portions of root crown, in place.

RESTORATION by Louis W. Amort RE2311, April 8, 1952 (Book 2, page 145, Tillamook County Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in ground; pipe bent over, out of place.

24" Fir stub bears N26W 39.7 ft.; now a 24" badly rotted stump with portions of scribes 1/4 S26 visible.

4" Fir bears S65E 15.1 ft.; missing.

Metal location poster on 52" Fir stump N80W 4.3 ft.; in place.

RESTORED February 11, 1988

Var. 21 1/2 E

Reset pipe in correct position, 26" in ground, in mound of rock and added marks "1988 LS1998", and from which a:

9" Hemlock bears S34W 15.5 ft. to face; scribed 1/4S26BT.

17" Hemlock bears S70E 28.7 ft. to face; scribed 1/4S25BT.

Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by David B. Buchholz and Clifford R. Foster.

Restored by



*Anthony J. Klosterman*

