CORNER RESTORATION FOR BOISE CASCADE CORP. IN T.1 N., R.9 W. OF THE WILLAMETTE MERIDIAN, TILLAMOOK COUNTY, OREGON. 1/4 CORNER COMMICN TO SECTIONS 8 AND 17.

ORIGINAL: G.L.O., 1884 by Henry Meldrum, contract #500.

6" Hemlock N 18° W 19 1ks. (12.5'); now 31", 30' tall (top broken off), N 18° W 12.5' to rotted face (no marks remaining), opened +-30 year old face and

found keel marks, no scribe marks.

15" Hemlock S 41° E 41 lks.(27.1'); now 28" uproot (root depression in place), I exposed face with scribe marks visible.

RESTORATION: 1959, Longview Fiber Co. (Book 2, page 507).
1" iron pipe; now in place. 12" Hemlock (original) N 18° W 12.5'; found in place, see above.

RESTORED: Set 1/2"X30" galvanized iron pipe with 3 1/2" aluminum cap, marked as shown, 28" in ground in center of found pipe.

5" Hemlock N 39° W 8.85' to 30d nail; "X" at BH, "BT" at base.

13" Hemlock S 71° E 12.7' to 30d nail; "1/4S17BT". **S17** 1989

Corner falls on spur ridge course N 30° E., Section corner 8,9,16 and 17 bears S 89° 41' 48" E (true from solar observation) PLS 1098, 2421.32' (record A-1335 = East 2347.8')

BT's have yellow metal location posters. New BT's have 30d nail with 1 1/2" aluminum disk "PLS 1098" in side center at base. Mag. variation 20 1/2° East.

All distances are to nail in side center of bearing trees.

DATED: June 2, 1989

WITNESSED BY: Stanly R. Cook

C. WAYNE COOK 3180 ALDERCREST ROAD TILLAMOOK, OREGON 87141

TILLAMOON COLL AUG 29 1989 VEPLEYORS OFFICE

REGISTERED PROFESSIONAL LAND SURVEYOR

101 OREGON JULY 22, 1977 C. WAYNE COOK 1096