TILLAMOOK COUNTY SURVEYORS OFFICE

Initial Point
Browns Addition
In Section 25 T.5S.,R.11W.,W.M



I found a 2" iron pipe with a wood plug and a brass nail approximately 1.0' deep in the sand. I set a 5/8" iron rod with a 3" brass cap inside of the found iron pipe and encased in a 10" concrete cylinder.

History of Found Monument

The found monument is the original monument for this subdivision, see Tillamook County Surveyors map #C- 263.

New Accessories

Power Pole #252501 bears 5.15*W. 3.17', the distance was measured to a finish nail with a brass washer in a scribed triangle on the East side of the pole.

4" spruce bears N.84*W. 10.24', the distance was measured to a finish nail with a brass washer in a small axe blaze on the Southerly side of the tree.

Location of Monument

This monument is located on South side of Mt. Angel Avenue in Neskowin.

In the presence of Dan McNutt & Al Dvorak

May 1990

Title:

TILLAMOOK COULT

SUPLEYORS OFF

1990

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 14, 1967 ALLAN E. DUNCAN 7 9 3

allan & Duncar, c.s.