## TILLAMOOK COUNTY SURVEYORS OFFICE

C 1/4 Corner of section 16 T.15., R.9W., W.M.

C1/4 S16 1963 RS 401 I found the O.S.B.F. 1 1/2" iron pipe with 3" bronze cap set in 1963, (See Tillamook County Surveyors map #A-1099), I encased in a 10" concrete cylinder.

## History of found monument

This corner was originally set for Oregon State Board of Forestry, by Richard A. Morris RS 401 in 1963, on the above said map, and the bearing trees set at that time to now be as follows:

28" Spruce S.14\*W. 18.0'; (now 52" stump, face overgrown, rusty O.S.B.F. yellow metal location poster attached).

13" alder S.40 1/2\*E. 5.9'; (found rotten log laying at approximate position).

White Cedar Post NW 1.0'; (found, laying down).

## New Accessories

\*72" light hat section post 1.5' North

\*indicates Tillamook County Surveyors yellow metal location poster attached.

## Monument location

This corner is located on a small spur ridge, in the corner of a recent clear-cut, SE, NE, & SW quadrants have been cut at this time.

In the presence of Dan McNutt and Al Dvorak

June 1990

Title:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1967
ALLAN E. DUNCAN
793

JUL **9** 1990

THLAMOOK COULT

TUSVEYORS OFFICE