## TILLAMOOK COUNTY SURVEYORS OFFICE

Section corner common to sections 16,17.20. & 21 T.3S.,R.10W.,W.M.

T3SR10W 17|16 --+---20121

I set a 10" cast iron monument case around a found 1 1/4" iron rod with a 3" Tillamook County Surveyors Brass cap, (See Tillamook County Surveyors Rewitness card #612), and encased in concrete.

History of found Monument

I found this monument to be as reported on the above said rewitness, and the accessories found and/or set at that time to now be as follows:

Metal bolt in concrete N.42\*E. 89.70'; (Now gone, sidewalk where the bolt was located and school are now N.R.F.P.D. gravel parking lot).

Power Pole BE-Y-128-GS S.57\*E. 35.36': (Found, now 35.29'. New number, #211800).

Power Pole BE-Y-128 S.53\*W. 37.72': (Found, now 37.82'. New number, #208800).

SE corner Bradley house N.42\*W. 73.93'; (Found, now 73.98', distance to the bottom of the third board of aluminum siding above the ground).

\*96" hat section post East 29.5': (Found, OK).

\* Indicates yellow Tillamook County corner tag affixed.

Surveys of reference not listed on rewitness card:

B-619	1971-72	Richard R. Kelley P.E.2652
A-3896	1979	John L. Carlich R.S.287
A-4243	1980	Frederick M. Gaylord L.S.929
A-5422	1986	Frederick M. Gaylord L.S.929
A-5520	1987	Allan E. Duncan L.S.793
Rewitness	book 4 page	24 1912 U.G. Jackson, County Surveyor
		113 1964 John L. Carlich, County Surveyor
		216 1971 John L. Carlich. County Surveyor
		84 1949 W.E. Anderson, County Surveyor
Field notebook "CT 17" page 53 1913 U.G. Jackson C.S.		
Survey book "S3" page 248 1899 A.M. Austin, C.S.		

## Monument Location

This corner is located approximately at the centerline intersection of Galloway County road with Sandlake County Road. The Bradley House mentioned above is the Sandlake store.

In the presence of Dan McNutt & Al Dvorak

