REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY 4907 Third St., Tillamook, Oregon 97141

Section corner common to Sections 11, 12, 13 and 14, T1N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL by Henry Meldrum, August 17, 1884. Post; missing.

- 12" Hemlock bears N47E 9 lks.; missing.
- 12" Hemlock bears S46E 100 lks.; missing.
- 18" Hemlock bears S54W 65 lks.; possible BT bears S57 1/2W 67 lks., now a 32" x 5 ft. high badly rotted stump with no marks visible.
- 14" Hemlock bears N33W 108 lks.; missing.

RESTORATION by Louis W. Amort RE2311, December 10, 1952 (Book 2, page 239, Tillamook County Records).

- 1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in ground, in mound of stone; now 36" in ground, in place.
 - 42" Fir stump bears N79 1/2E 123.4 ft.; now 3 ft. high, badly rotted with no scribes visible.
 - 48" Fir stump bears S39 1/2E 66.3 ft.; now 6 ft. high, rotted with scribes T1N R8W S13 BT visible.
 - 51" Fir snag bears N57W 152.4 ft.; now 6 ft. high rotted stump with scribes T1N R8W S11 BT visible.

REWITNESSED November 1, 1990

Var. 21 1/2 E

From the above pipe with marks "LS1998 1990" added a:

- 10" Alder bears N31E 19.0 ft. to barkscribes T1NR8WS12BT.
- 10" Fir bears S25 1/2E 48.5 ft. to face scribed T1NR8WS13BT.
- 14" Fir bears S03 1/2W 33.2 ft. to face scribed T1NR8WS14BT. 10" Fir bears N75 1/2W 23.6 ft. to face; scribed T1NR8WS11BT.

Metal location poster on new BTs.

3/4" brass washer marked "LS1998" nailed to face of new BTs. Present and witnessed by Clifford R. Foster.

Rewitnessed by Navid B. Buckhor under my direction. David B. Buchholz, £\$2272

> REGISTERED **PROFESSIONAL** AND SURVEYOR

OREGON ANTHONY J. KLOSTERMAN 1998

19 1990 PLEYORS OFFICE