TILLAMOOK COUNTY SURVEYORS OFFICE COURT HOUSE, TILLAMOOK, OREGON 97141

1/4 CORNER COMMON TO SECTIONS 8 & 17 T.1S., R.8W., W.M.

1	S 8
/	+
4	S17
	1991

I found a 5/8"X 36" iron rod approximately 6" deep in the East bound lane of Oregon State Highway #6 (Wilson River Highway). I set a 5/8"X 12" iron rod with a 3" Tillamook County Surveyors Brass cap in a 8" cast iron monument case at the position of the found iron rod.

History of found monument

The found monument fit well with the brass cap reference monuments found on the right of way of said highway:

SECT 8/17 . T1SR8W WC 77.70 FT BLM 1958

1/4 SEC COR

I found a brass cap in concrete 4" deep in a gravel driveway, stamped as shown at left, West 77.63'. This R.M. was set by the State Highway Department (see T.C.S. Map #F-21-29). The BLM apparently stamped the monument later, the lettering "BLM 1958" is a smaller size than the rest.

1/4 SEC COR SECT 8/17 I found a brass cap in concrete 1" deep, stamped as shown at left, East 52.53'. This R.M. was set by the State Highway Department (see T.C.S. Map #F-21-29). The BLM apparently stamped the monument later, the lettering "BLM 1958" is a smaller size than the rest.

WC 52.60 FT BLM 1958

Using the above RMs as a basis of bearings of East I found the following monuments, located relative to the corner:

5/8" iron bar, approximately 1" deep in a gravel driveway, N.O 07'E. 60.67', slightly bent, I used the top. (T.C.S. Map #A-2359) .

1 1/2" iron pipe, 2" high, S.0 18'W. 40.58'. (T.C.S. Map #A-464).

No original evidence was found at this time.

New Accessory

72" light hat section post S.32 E. 1.5' of East R.M.

*indicates Tillamook County Surveyors yellow metal location poster attached.

REGISTERED PROFESSIONAL LAND SURVEYOR

Page 1 of 2

OREGON JULY 14. 1967 ALLAN E. DUNCAN 793

JUN 13 1991

Surveys and Rewitnesses of Record

B-892	3-1980	Frederick M. Gaylord	LS	929	
A-51	9-1941	A.H. Gulstrom stamped			
		signed) W.E. Anderson	PE	1697	
A-133	9-11-38	W.E. Anderson	PE	1697	
A-290	4-30-48	W.E. Anderson	PE	1697	
A-436	8-1950	W.E. Anderson	PΕ	1697	
A-463	1951	W.E. Anderson	PΕ	1697	
A-464	?	W.E. Anderson	PE	1697	
A-501	10-1951	W.E. Anderson	PE	1697	
A-538	1952?	W.E. Anderson	PE	1697	
A-790	6-1959	John L. Carlich	RS	287	
A-1009	5-1962	Richard A. Morris	RS	401	
A-1279	10-1965	Wilbur A. Markham	PΕ	1842	
A-1657	11-16-67	Wilbur A. Markham	PE	1842	
A-1717	11-12-68	Lester E. Fultz		4571	
A-1722	5~1969	John L. Carlich		287	
A-1729	4-18-69	Wilbur A. Markham		1842	
A-2359	1-1973	John L. Carlich	RS	287	
A-2950	10-1975	John L. Carlich	RS	287	
A-4130	11-1977	John L. Carlich	RS	287	
F-21-29	2-8-36	0.S.H.D.			
T.C.S. Survey Book S3				1118	
T.C.S. Field notebook			PΕ	1697	
Also see many ties in field notebook bins S 17 & S 8, 1S8.					

Location of Monument

This corner is located approximately in the middle of the East bound lane of Oregon State Highway #6, SE of the Wilson River General Store.

In the presence of Dan McNutt & Allen Dvorak

May 21, 1991

Title:

REGISTERED PROFESSIONAL LAND SURVEYOR

Page 2 of 2

OREGON
JULY 14, 1967
ALLAN E. DUNCAN
7 9 3

