TILLAMOOK COUNTY SURVEYORS OFFICE COURT HOUSE, TILLAMOOK. OREGON 97141

1/4 CORNER COMMON SECTIONS 10 & 15 T.1N., R.10W., W.M.

1 S10 / ---+---4 S15 1960 RS 401 I found a 1 1/2" iron pipe with a 3" Oregon State Board of Forestry Bronze Cap (see T.C.S. Rewitness Book 2 at Page 446). I encased the found I.P. in a 10" concrete cylinder.

History of found monument

I found this monument to be as described on said T.C.S. Rewitness and the references found and/or set at that time to now be as follows:

Original 40" hemlock S.20°E. 17 lks., reported on above as a 48" hemlock stub 2' high face and scribes rotted away; (Now gone) .

Original 36" hemlock N.10°W. 30 lks., reported on above as N.10°W. 33 lks. a 37" uproot backcast of scribes "BT" visible, both faces rotted away, roots and root hole in place; (Found, now a rotten pile of wood, unidentifiable).

(Book 2 Page 446) 12" Hemlock N.55 $1/2^\circ$ E. 16.0'; (Found, now a 12" stub 3' tall ,rotten, scribing visible on partially healed face.

(Book 2 Page 446) 16" Hemlock S.30 1/2°E. 14.4'; (Found, now a 21" rotten stump 5' tall, face overgrown).

(Book 2 Page 446) 4"X 4"X 48" white painted cedar post 1.0' NE; (Found, rotted off).

New Accessory

*72" light hat section post North 1.6'.

*indicates Tillamook County Surveyors yellow metal location poster attached.

Surveys and Rewitnesses of record

B-437 9-1964
Rewitness Book 2 page 446 12-02-60
A-1206 9-1964
G.L.O. Book 1N10 Page 43 7-11-1873

9-1964 Richard A. Morris RS 401 12-02-60 Richard A Morris RS 401 9-1964 Richard A. Morris RS 401

173

Location of Monument

This corner is located approximately 50' Westerly of a gravel logging road in small replanted trees. No trees of sufficient size for bearing trees at this time.

In the presence of Al Dvorak and Dan McNutt

June 11, 1991

Title

JUL 8 1991

REGISTERED PROFESSIONAL LAND SURVEYOR

Allan & Duncan, C.S.

OREGON JULY 14. 1967 ALLAN E. DUNCAN 7 9 3