

TILLAMOOK COUNTY SURVEYORS OFFICE  
COURTHOUSE, TILLAMOOK, OREGON 97141

SE CORNER VAUGHN DLC #37, SECTION 12 T.1S., R.10W., W.M.

S E I found a 1 1/4" iron rod with a 3" Tillamook County  
S12| VAUGHN Surveyors Brass Cap (see T.C.S. Rewitness #290). 3"  
----+DLC deep in the apparent centerline of Hathaway Road. I  
#37 set an 8" cast iron monument case around the found  
RS 287 monument and encased in concrete.  
1973

-----  
History of found monument

I found this monument to be as described in said T.C.S. Rewitness and the references found and/or set at that time to now be as follows:

SE corner of barn 25.0'; (Found, N.53°W. 25.0' to the corner of a concrete wall).

NE corner of barn 55.44'; (Found, N.20°W. 55.5' This corner is in bad shape and hard to measure to with any accuracy).

\*86" hat section post N.15°E. 14.5'; (Found, N.15°E. 15.8').

\*indicates Tillamook County Surveyors yellow metal location poster attached.

-----  
New Accessories

Power Pole #125601 N.85°W. 132.67'. Distance was measured to a bridge spike found in the side center of the pole.

5/8" iron rod with a red plastic cap in a fence line S.7°W. 13.52'.

-----  
Surveys and Rewitnesses of record not listed on rewitness #290

A-4446	4-30-81	Allan E. Duncan LS 793
B-56	?	?


-----  
Location of Monument

This corner is located in the apparent centerline of Hathaway Road (A.K.A Vermilyea Road).

-----  
In the presence of Al Dvorak and Dan McNutt

September 18 1991

Title:



*Allan E. Duncan, C.S.*

