TILLAMOOK COUNTY SURVEYORS OFFICE COURT HOUSE, TILLAMOOK, OREGON 97141

1/4 CORNER COMMON SECTIONS 9 & 10 T.3S., R.10W., W.M.

T3SR10W I found a 2" iron pipe with a 3" Bureau of Land
1/4 Management Brass Cap, (see T.C.S. Rewitness Book 6
| Page 98). I encased the found iron pipe in a 10"
S9+S10 concrete cylinder.
|
1978

History of found monument

I found this monument to be as described in T.C.S. Rewitness Book 6 at page 98 and the references found and/or set at that time to now be as follows:

(Original) 10" hemlock N.85*E. 16 lks., reported on T.C.S. rewitness card #602 as a 20" blown down hemlock with healed witness face, and by B.L.M. in said Rewitness Book as a decayed hemlock snag with scribe marks visible; (Found, now a rotten uproot scribing 1/4S BT visible. The face is located approximately 2' Westerly of the new NE Bearing Tree).

(Rewitness Card #602) 6" hemlock S.42*E 14.4', reported in Book 6 Page 98 as an 8" hemlock S.44*E. 21 1/2 lks with healed blaze; (Found, now an 11" hemlock with healed blaze S.42*E. 13.96' to a finish nail with a brass washer in a small blaze).

(Rewitness Card #602) 10" hemlock N.31*W 10.3', reported in Book 6 Page 98 as a 16" hemlock N.31*W. 16 lks with healed blaze; (Found, now a 20" hemlock with healed blaze N.25*W. 9.31' to a finish nail with a brass washer in a small blaze).

I also found a steel fence post with a U.S.F.S. yellow attention tag 3.2' Southerly and an orange painted 1/2" X 60" iron pipe driven 2' in the ground Easterly 0.8'.

New Accessories

*14" hemlock N.77*E. 14.09' scribed 1/4S10BTCS. Measurements were taken to a finish nail with a brass washer between th B and the T.

*19" hemlock S.50*W. 18.32' scribed 1/4S9BTCS. Measurements were taken to a finish nail with a brass washer between th B and the T.

*84" light hat section post North 1.4'.

 $\mbox{\tt \#indicates}$ Tillamook County Surveyors yellow metal location poster attached.

Surveys and Rewitnesses of record

B-833
Rewitness Book 6 page 98 & 50
Rewitness Card #602
G.L.O. Book 3S10 Page 31

O4-13-1979
Larry D. Bishop LS 896
B.L.M.
Leonard Whitmore Deputy C.S.
William P. Wright
Contract #442

Location of Monument

This corner is located approximately 100' Northerly of a small creek in a thick stand of hemlock trees. I also found a U.S.F.S. yellow metal location poster on a 13" fir approximately 30' Southwest of a logging road inscribed "stay on ridge approx. S.50*W. 600' to 1/4 corner".

In the process of Al Dyspak and Dan MoNett

In the presence of Al Dvorak and Dan McNutt

October 9, 1991

Title



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 14, 1967
ALLAN E. DUNCAN
793