REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY 4907 Third St., Tillamook, Oregon 97141

Section corner common to Sections 20, 21, 28 and 29, T1S, R7W, W.M., Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, October 1, 1891. Post; missing.

- 20" Fir bears S71 1/2W 31 lks.; now a 24" badly rotted snag with scribes S29 visible. Cruiser marks visible above face.
- 24" Hemlock bears N81 1/2W 28 lks.; now a badly rotted root crown, bears N88 1/2W.
- 14" Hemlock bears S38E 25 lks.; missing. 40" Fir bears N57 1/2E 44 lks.; now a 50" badly rotted stump with axe work visible on rotted out face.

RESTORATION by Louis W. Amort RE2311, November 19, 1952 (Book 2, page 235, Tillamook County Records).

- 1 1/2"x36" galvanized iron pipe with 3" bronze cap, 30" in ground; now in place, in mound of stone.
 - 66" Fir stump bears N58 1/2E 37.6 ft.; now rotted with scribes T1S R7W S21 BT RE231 visible.
 - 50" Fir stump bears S81 1/2E 31.0 ft.; now badly rotted with scribes S28 BT visible.
 - 65" Fir stump bears S46 1/2W 34.7 ft.; now badly rotted with no scribes visible.

REWITNESSED May 14, 1992

Var. 19 1/2E

From above pipe with marks "LS1998 1992" added a:

- 9" Fir bears S29W 20.6 ft. to face; scribed T1SR7WS29BT. 8" Fir bears S34E 12.6 ft. to face; scribed T1SR7WS28BT.
- 9" Fir bears N51W 14.2 ft. to face; scribed T1SR7WS20BT.
- 12" Fir bears N16E 25.6 ft. to face; scribed T1SR7WS21BT.

Metal location poster on new BTs.

Also 1952 metal location poster on Original 20" Fir BT.

3/4" brass washer marked "LS1998" nailed to face of new BTs.

Present and witnessed by David B. Buchholz.

Rewitnessed by

REGISTERED PROFESSIONAL LAND SURVEYOR

Onthony Onegon
JULY 16, 1982
ANTHONY J. KLOSTERMAN 1998

TILLAMOOK JUN 17 1992 CALEYORS OFFICE