REWITNESSED CORNER OREGON DEPARTMENT OF FORESTRY 4907 Third St., Tillamook, Oregon 97141

One quarter corner common to Sections 35 and 36, T1S, R7W, W.M., Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, September 14, 1891. Post; missing.

- 16" Hemlock bears N24W 19 lks.; now a 24" x 30" high badly rotted stump with no scribes visible, bears N13W
  - 8" Hemlock bears N57E 49 lks.; missing, point falls in old cat road.

RESTORATION by Richard A Morris LS401, October 17, 1960 (Book 2, page 459, Tillamook Co. Records.)

- 1 1/2"x36" glavanized iron pipe with 3" bronze cap, 33" in ground, in mound of stone; in place, on north edge of old cat road, course N44E by S68W.
  - 34" Fir stump bears N77E 36.2 ft.; now rotted with scribes 1/4 S36 BT visible.
  - 28" Fir stump bears N11 1/2W 15.0 ft.; now badly rotted with face laying alongside with scribes 1/4 S35 BT visible.
  - 4"x4"x72" white painted Cedar post 1.0 ft. NE of pipe; now rotted and out of place.

REWITNESSED October 21, 1993

Var. 19 1/2 E

From above pipe with marks "LS1998 1993" added, a:

- 10" Fir bears N84E 26.7 ft. to face; scribed 1/4S36BT.
  15" Fir bears S33 1/2E 21.9 ft. to face; scribed 1/4S36BT.
  21" Fir bears S88 1/2W 36.0 ft. to face; scribed 1/4S35BT.

Metal location poster on new BTs. Also 1955 metal location posters on Morris' BTs. 3/4" brass washer marked "LS1998" nailed to face of new BTs. Present and witnessed by Clifford R. Foster.

Rewitnessed by David B. Buckhor under my direction. David B. Buchholz, LSØ272

> REGISTERED **PROFESSIONAL** LAND SURVEYOR

Cinthon & Chaterman JULY 16, 1982 ANTHONY J.KLOSTERMAN

1998

THIAMOOK COULT NOV 10 1993 EAVEYORS OFFICE

Expires 12/31/93