REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY 4907 Third St., Tillamook, Oregon 97141

Section corner common to Sections 9, 10, 15 and 16, T1S, R7W, W.M., Tillamook County, Oregon.

ORIGINAL by Albert P. Wilson, October 20, 1891. Post; missing.

36" Hemlock bears N76W 127 lks.; now a 46" x 40' high badly rotted snag with no scribes visible.

35" Hemlock bears S88W 172 lks.; now a 26" badly rotted uproot laying on face.

10" Cedar bears S87E 132 lks.; missing. 10" Cedar bears N64E 105 lks.; missing.

RESTORATION by Richard A. Morris LS401, October 25, 1957 (Book 1, page 307, Tillamook County Records).

1 1/2"x36" galvanized iron pipe with 3" bronze cap, 33" in ground; now in place, in fill slope of cat road.

30" Cedar snag bears N51E 87.5 ft.; now a badly rotted windfall, out of place with portions of scribes T1S R7W visible.

79" Fir snag bears N87W 101.5 ft.; now a 5 ft. high badly rotted stump with no scribes visible.

62" Fir stump bears S74E 102.0 ft.; now rotted with scribes T1S R7W S15 BT RS4 visible.

4"x4"x60" White painted Cedar post 1.0 ft. SE of pipe; missing.

REWITNESSED January 31, 1994

Var. 19 1/2E

From above pipe with marks "LS1998 1994" added a:

13" Fir bears S57E 10.9 ft. to face; scribed T1SR7WS15BT.

- 10" Fir bears N57 1/2E 27.6 ft. to face; scribed T1SR7WS10BT.
- 9" Fir bears N39 1/2W 26.0 ft. to face; scribed T1SR7WS9BT.
- 15" Fir bears S87 1/2W 45.2 ft. to face; scribed T1SR7WS16BT.
- 6 ft. Orange Carsonite post bears N11E 1.0 ft. from pipe. Centerline of cat road bears East 24.0 ft. bears N33E by S40W.

Metal location poster on new BTs. 3/4" brass washer marked "LS1998" nailed to face of new BTs. Present and witnessed by Clifford R. Foster and David B. Buchholz.

Rewitnessed by

REGISTERED **PROFESSIONAL** LAND SURVEYOR

androny & Staterman OREGON JULY 16, 1982

ANTHONY J.KLOSTERMAN 1998

TILLAMOON COUNT MAR 2 1994 CALEFORS OFFICE

Expires 6/30/95