RESTORED CORNER FOR OREGON DEPARTMENT OF FORESTRY 4907 Third St., Tillamook, Oregon 97141

Southwest one sixteenth corner to Section 11, T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL by Richard A. Morris LS401, December 31, 1959 (Book 2, page 417, also Plat #B-419, Tillamook County Records).

- 1 1/2"x36" galvanized iron pipe with 3" bronze cap, 34 " in ground; found, out of place.
 - 15" Hemlock bears N45E 4.6 ft.; now aa 18" x 7 ft. high badly rotted stub with portions of scribes visible.
 - 12" Hemlock bears S87W 7.9 ft.; now portions of root crown in place.
 - Metal location poster on 9" hemlock bears N18W 1.0 ft.; now a badly rotted uproot with tag laying on ground.
 4"x4"x60" white painted Cedar post 1.0 ft. SE of pipe; missing.

RESTORED October 20, 1994

Var. 19 1/2 E

Reset above pipe with marks "LS1998-1994" added, 35" in ground a:

- 22" Hemlock bears N81E 31.1 ft. to face; scribed SW1/16S11BT.
- 8" Fir bears S24W 11.5 ft. to face; scribed SW1/16S11BT. 9" Fir bears N71W 29.6 ft. to face; scribed SW1/16S11BT.

Metal location poster on new BTs. 3/4" brass washer marked "LS1998" nailed to face of new BTs.
Present and witnessed by David B. Buchholz and Clifford R. Foster.

Restored by

TILLAMOOK NOV 17 1994 CLEVORS OF

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OMEGON July 21, 1982 Anthony J. Klosterman 1998

appoint

Expires 6/30/95

convited