
# TILLAMOOK COUNTY SURVEYORS OFFICE COURT HOUSE, TILLAMOOK, OREGON 97141

CN 1/16 CORNER SECTION 3, T.2S.,R.9W.,W.M.



I found a 2" iron pipe with a 3" Tillamook County Surveyors Brass Cap, (see T.C.S. Rewitness Card #349), I set an 8" cast iron monument case around the found monument and encased in concrete, flush with the surface of the pavement.

### History of found monument

I found this monument to be as described on said T.C.S. Rewitness #349 and the references found and/or set at that time to now be as follows:

(Book 5 Page 102) Witness Corner 1" iron pipe with a 1 1/2" steel cap South 10.24', see field notes for Sander in field note bin S3 2S9; (not found).

(Rewitness Card #349) Power Pole D20-58 S83°E 130.22'; (Found, at bearing and distance).

(Rewitness Card #349) 20 Spruce N16 W 72.15; (Found, now 43 rotten stump, at bearing and distance).

(Rewitness Card #349) \*96" hat section post 9.29' South (Found, at bearing and distance).

#### New Accessory

Power Pole #035603 bears S9'W 9.21' to a punched monument spike in a scribed triangle in the side center of the pole.

\*indicates Tillamook County Surveyors yellow metal location poster attached.

## Surveys and Rewitnesses of record

P-42	4/02/1991	A. DUNCAN	LS	793	A-4051	1/1980	C. W	. COOK	LS	1098
B-301	4/1951	W. ANDERSON	PΕ	1697	A-3784	4/1979				
B-1252		C. W. COOK			A-2659	9/1974	J. C	ARLICH	RS	287
B-1883	5/19/1995					11/1970				287
B-1859	1/13/1995	R. LARSON	LS 2	2102	A-6721	11/3/93	T. J0	DNES	LS	2507
B-1785	4/27/1994	R. LARSON	LS 2	2102	A7078	12/6/95	T. J0	ONES	LS	2507
REWITNES	S BOOK 5 AT	PAGE 102 6/2	22/6	5 J.	CARLICH RS	287, TILL.	COUN	nty sur/	/EYO!	₹
		11/03/70 J.								

## Location of Monument

This corner is located on the south side of Chance County Road in the west side of a paved driveway apron.

In the presence of Al Dvorak and Dennis Wood

March 12, 1996

Title

