## REWITNESSED CORNER FOR OREGON DEPARTMENT OF FORESTRY 4907 Third St., Tillamook, Oregon 97141

Section corner common to Sections 25, 30, 31 and 36, T1S, R6&7W, W.M., Tillamook and Washington Counties, Oregon.

ORIGINAL by Albert P. Wilson, May 14, 1891. Post; missing.

- 20" Hemlock bears N78½°E 73 lks.; now a 13" x 4½ ft. high badly rotted stub. Portion of face with scribes found laying on the ground.
- 28" Hemlock bears S58°E 24 lks.; now a 20" x 5½ ft. high badly rotted stub with no scribes visible.
- 20" Hemlock bears S76°W 53 lks.; missing.
- 10" Hemlock bears N09% W 68 lks.; missing.

RESTORATION by L.H.L. Lumber Corporation, 1951 (unrecorded).

1" galvanized iron pipe with 2 ½" bronze cap; in place 5 inches above ground, but loosely set.

REWITNESSED by Louis W. Amort RE2311, May 7, 1952 (Book 2,page 202, Tillamook County Records).

- 4" Hemlock bears N12½°E 21.5 ft.; now 12" with face closed.
- 46" Fir snag bears S58°E 47.3 ft.; now a 4½ ft. high rotted stump with scribes T1SR6WS31BT visible.
- 40" Fir snag bears S22°W 14.5 ft.; now a 5 ft. high rotted stump with scribes SR7WS6BT visible.
- 18" Hemlock bears N70½°W 62.9 ft.; now an 18" x 20 ft. high rotted snag with scribes T1SR7WS25BTRE2311 visible.

NOTE: Distances measured to center of original BTs.

REWITNESSED December 10, 1996

Var. 19⅓°E

From above pipe with marks "LS2272 1996" added a:

- 14" Hemlock bears S43½°E 5.6 ft. to face; scribed T1SR6WS31BT.
- 18" Hemlock bears S73%°W 33.15 ft. to face; scribed T1SR7WS36BT.
- 18" Hemlock bears N62%°W 36.3 ft. to face; scribed T1SR7WS25BT.

Metal location poster on new Bts and Amort's 40" Fir snag. 3/4" brass washer marked "LS2272" nailed to face of new Bts. 6 ft. Orange carsonite post beams N45°W 1.75 ft. Present and witnessed by Clifford R. Foster.

Restored by



SURVEYED BY:

REGISTERED PROFESSIONAL LAND SURVEYOR

David B. Buchho &

OREGON
July 16, 1987
David B. Buchholz
2272

4907 Third Street TILLAMOOK, OR 97141 EXPIRES DECEMBER 31, 1997