OREGON CORNER RESTORATION FORM

Township 1 North Range 7 West Sections 4 & 9

County: Tillamook Date: 7-25-1997

Corner Designation: 1/4 Corner 4/9 X Referenced Out

Previous Renewals/Surveys, etc: Not researched, also did not have GLO notes.

Monument Found (Condition and Source) : Found 3" brass cap on 2"o.d. galvanized iron pipe, 10" above ground surface, marked as shown below, in a mound of 1-foot diameter rounded rocks. Note: Oregon LS#199 = Lyle Beyers.

Accessories Found: None

Monument Detail



Sketch



Monument Set: None

New Accessories: Nailed a yellow aluminum Willamette Industries tag to the following:

- 7"dbh Cascara which has a split stem at 7' high, bears N58E, 16.5 feet
- 21"dbh limby Douglas-fir, N80E, 50 feet
- 9"dbh Willow, S28W, 14 feet

A 5-foot diameter old log chunk is approximately East, 20 feet.
Several large old logs are SE about 50 feet.

TILLAMOOK COUNTY AUG 12 1997 SURVEYORS OFFICE

Location & Comments: Corner falls just NW of the edge of a vine maple flats.

Hand Compass Declination: 20E
Firm/Agency: Willamette Industries
North Coast Timber & Logging
PO Box 998
Seaside, OR 97138
Party Chief: Andy Blachly
Notes: Andy Blachly
Witness:

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 26, 1985 ANDREW T. BLACHLY 2168