TILLAMOOK COUNTY SURVEYORS OFFICE COURT HOUSE, TILLAMOOK DREGON 97141

SECTION CORNER COMMON SECTIONS 1, 2, 11, and 12, T.1N., R.10W., W.M.

T1NR10W 22 | 21 S11 S12 RS 287 1974

I FOUND A 2' IRON PIPE WITH A 3' TILLAMOOK COUNTY SURVEYORS BRASS CAP IN A 10' RED CLAY TILE REWITNESS

HISTORY OF FOUND MONUMENT

I FOUND THIS MONUMENT TO BE AS DESCRIBED IN TILLAMOOK COUNTY SURVEYORS REWITNESS CARD #15 AND THE REFERENCES FOUND AT THAT TIME TO NOW BE AS FOLLOWS:

(G.L.O.) 75° SPRUCE S.84°W 19 LINKS, REPORTED IN REWITNESS BOOK 10 AT PAGE 68 AS A 75° SPRUCE S.34°E. 19 LINKS, AND REPORTED, IN REWITNESS BIN CARD #15, AS A 75° SPRUCE STUMP S.34°E. 19 LINKS = 12.54°, WITH VISIBLE SCRIBING, (NOW A 75° SPRUCE STUMP, 25° TALL, VERY ROTTED, ± 10 SMALL TREES GROWING DUT DF IT, NO SCRIBING VISIBLE, S.34°E. 12.54°).

(G.L.O.) 24" HEMLOCK N.40°E. 14 LINKS, REPORTED IN REWITNESS BOOK 10 AT PAGE 68 AS A 24" HEMLOCK N.40°E. 14 LINKS, AND REPORTED, IN REWITNESS BIN CARD #15, AS A STUMP WITH YELLOW TAG, N.40°E. 14 LINKS = 9.24', (NOW A 54" HEMLOCK STUMP, 7' TALL, VERY ROTTED INSIDE, BARK SHOWS SIGNS OF DVERGROWN FACE N.40°E. 9.24').

(BOOK 3 PAGE 12) 36° SPRUCE N.76°W. 31.5', REPORTED, IN REWITNESS BIN CARD #15, AS A STUMP WITH FACE; (NOW GONE, FALLS AT THE EDGE OF A CLEARED FIELD).

(BOOK 3 PAGE 12) 30" HEMLOCK S.2"E. 24.8", REPORTED, IN REWITNESS BIN CARD #15, AS A STUMP WITH FACE, (FOUND, NOW ONLY A PILE OF ROT REMAINS).

(BOOK 3 PAGE 12) 36' SPRUCE S.25'W. 38.0', REPORTED, IN REWITNESS BIN CARD #15, AS A STUMP WITH FACE, (FOUND, NOW 25' X 4' HIGH ROTTED STUMP, NO MARKS

(REWITNESS BIN CARD #15) 84" HAT SECTION POST 1.2' EAST; (FOUND, REPLACED MISSING YELLOW METAL LOCATION TAG).

NEW ACCESSURIES

*30" HEMLOCK N.67°E. 18.36", SCRIBED "TINRIOWSIBTCS".

*18" HEMLOCK S.7°E. 12.95", SCRIBED "TINRIOWS12BTCS".

THE DISTANCES WERE MEASURED TO A BRASS WASHER WITH A TACK IN THE FACE BETWEEN THE SCRIBE MARKS 'B' & 'T'.

*Indicates Tillamook County Surveyors yellow metal location poster attached,

SURVEYS AND REWITNESSES OF RECORD

B-419 B-437 A-3209 A-3213	5-10-74 4-29-15 1-4-1889 7-18-50 DECEMBER 1959 3-20-61 JUNE 1977 MAY 1977	JOHN L. CARLICH RS 287 H.P. KERR DEPUTY C.S. TILLAMOOK COUNTY SURVEYOR LONGVIEW-FIBER CO. R.A. MORRIS RS 401 R.A. MORRIS RS 401 C.H. HANDFORTH P.E. 3510 C.H. HANDFORTH P.E. 3510
A-5314	11-07-85	R. LARSON L.S. 2102
G.L.O. CONTRACT #183	JULY 1873	C.J. HANDLEY

MONUMENT LOCATION

THIS MONUMENT IS LOCATED APPROXIMATELY 150' SOUTH OF WALDRON CREEK ON THE EAST SIDE OF A CLEARED FIELD. THE CENTER POLE, OF P.P. & L. 3 POLE STRUCTURE #6/47, BEARS APPROXIMATELY S.61'W. 195'. ATTACHED T.C.S. YELLOW METAL LOCATION POSTER.

IN THE PRESENCE OF DAN MCNUTT AND AL DVORAK

MAY 4, 1998

Title

THLAMOOK COLLY MAY 18 1998 Exterors OFFICE

REGISTERED **PROFESSIONAL** LAND SURVEYOR

Ran 2. Vuncan, C.S OREGON JLY 14, 1967 E. DUNCAN

793

EXPIRES 12-31-99

274