TILLAMOOK COUNTY SURVEYORS OFFICE COURT HOUSE, TILLAMOOK OREGON 97141

SECTION CORNER COMMON SECTIONS 7,8,17,& 18 T.3S.,R.10W.,W.M.

T3SR10W S 7|S 8 S18|S17 RS 287 1971

I FOUND A 3" TILLAMOOK COUNTY SURVEYORS BRASS CAP IN 10" RED TILE AND CONCRETE, 3' BELOW THE SURFACE OF THE SAND.

T3SR10W S 7 S 8 S18 S17 LS 793 1998 I SET A 1 1/2" IRON PIPE WITH A 3" TILLAMOOK COUNTY SURVEYORS BRASS CAP IN AN IRREGULAR MASS OF CONCRETE, AT THE SURFACE OF THE SAND, OVER THE FOUND MONUMENT, APPROXIMATELY 3' DEEP.

HISTORY OF FOUND MONUMENT

I FOUND THIS MONUMENT TO BE AS DESCRIBED IN T.C.S. REWITNESS BOOK #594 AND THE REFERENCES FOUND AND/OR SET AT THAT TIME TO NOW BE AS FOLLOWS:

(BOOK 4 PAGE 51) 10" PINE S.34"15'W. 300.00', REPORTED ON REWITNESS CARD #594 AS A SCHOOL MARM PINE SCRIBING VISIBLE; (NOT FOUND).

(BOOK 4 PAGE 51) 6" PINE S.5'35'E. 533.3', REPORTED IN ON REWITNESS CARD #594 AS GONE, REPORTED ON TILLAMOOK COUNTY SURVEYORS MAP B-1226 AS A 12" PINE S.5 1/2'E. 533.3' SCRIBING VISIBLE; (FOUND, NOW 14" PINE, SCRIBING VISIBLE ON PARTIALLY HEALED FACE, AT POSITION).

(BOOK 5 PAGE 217) 5" PINE N.27"W. 68.83', REPORTED ON REWITNESS CARD #594 AS A 9" PINE SCRIBING VISIBLE, REPORTED ON TILLAMOOK COUNTY SURVEYORS MAP B-1226 AS A 10" PINE N.20"W. 69.0'; (FOUND, FACE HEALED, NOW 13" PINE, LEANING HEAVILY, N.20"W. 68.0' TO THE CENTER, 67.37' TO A NAIL WITH A BRASS WASHER IN A SMALL BLAZE FACING THE CORNER).

(BOOK 5 PAGE 217) 2" IRON PIPE S.17"W. 50.00', REPORTED ON REWITNESS CARD #594 AS FOUND, RUSTED-O.K., REPORTED ON TILLAMOOK COUNTY SURVEYORS MAP B-1226 AS FOUND; (FOUND, NOW 3' DEEP IN SAND, AT POSITION).

(REWITNESS #594) 96" HAT SECTION POST 1.45' EAST, (FOUND, NOW 0.2' OF THE TOP IS ABOVE THE SAND, AT POSITION).

(REWITNESS #594) 6" PINE S.75"E. 152.72"; (FOUND, NOW 16" PINE, FACE HEALED, AT POSITION).

(REWITNESS #594) 5" PINE S.20"W. 56.65", REPORTED ON MAP B-1226 AS A 12" PINE S.20"W. 56.5"; (FOUND, LEANING HEAVILY ON BRANCHES, ALMOST HORIZONTAL, 55.5", TO THE CENTER OF THE TREE, FACE HEALED).



PAGE 1 OF 2

NEW ACCESSORY

- *72" LIGHT HAT SECTION POST SOUTH 1.5'.
- *INDICATES TILLAMOOK COUNTY SURVEYORS YELLOW METAL LOCATION POSTER ATTACHED.

SURVEYS AND REWITNESSES OF RECORD

| REWITNESS BOOK 4 PAGE | 51 | 111848 | TILLAMOOK COUNTY SURVEYOR |
|-------------------------|--------|---------------|--------------------------------------|
| REWITNESS BOOK 4 PAGE | 77 | 11-18-48 | TILLAMOOK COUNTY SURVEYOR |
| REWITNESS BOOK 1 PAGE | 89 | 11-18-48 | TILLAMOOK COUNTY SURVEYOR |
| REWITNESS CARD #600 | | 5-16-63 | LEONARD WHITMORE U.S.F.S. |
| REWITNESS CARD #594 | | 12-24-71 | |
| REWITNESS BOOK 5 PAGE | | 70666 | |
| B-1458 | | 9-05-90 | |
| B-1655 | | 9-08-92 | |
| 5 1000 | | 5 00 52. | & MICHAEL SCHWARTZ LS 1922 |
| B-1698 | | 7-13-87 | |
| B-292 | TANI | & FEB. 1951 | |
| | OMIN. | ** | • |
| F-27-25 | | | JAY BOYD PE 5180 |
| F-28-18 | | MARCH 1970 | JAY BOYD PE 5180 |
| P-424 | | 12-15-97 | ALLAN E. DUNCAN LS 793 |
| B-1226 A & B | AU(| GSEPT. 1986 | JIM PETERSON LS 1084 |
| B-1374 | MAY | -JUNE 1989 | LARRY BISHOP LS 896 |
| BOOK X PAGE 4.5.13. & : | 25 FIE | ELD NOTES FOR | MAP B-292 FIELD NOTE BIN "S18 3S10". |

MONUMENT LOCATION

THIS CORNER IS LOCATED APPROXIMATELY 2.5' NW OF A SOUTH X EAST FENCE CORNER, AT THE SOUTHERLY EDGE OF A SAND FIELD USED BY ALL TERRAIN VEHICLES FOR RECREATIONAL PURPOSES.

IN THE PRESENCE OF DAN MCNUTT AND AL DVORAK

NOVEMBER 24, 1998

Title:

JAN 21 1999

LAND SURVEYOR

OREGON
JULY 14, 1967
ALLAN E. DUNCAN

793 EXPIRES 12-31-99

REGISTERED

PROFESSIONAL

PAGE 2 OF 2