RESTORATION OF THE SECTION CORNER COMMON TO SECTIONS 20, 21, 28, AND 29, T3N, R9W, W.M.

At the corner I find the remains of the corner tree and four bearing trees scribed by David Buchholz in 1981 and reported by Loren R. Steele, PLS 1662, in Tillamook County Surveyor's Re-witness Book 6, Page 173. The corner tree and southeast bearing tree are now blowdowns with attached rootwads. I open and tie the scribed faces of the northeast, southwest, and northwest B.T.'s, and at record distances from said faces I set 36" in the ground a 2" x 36" galv. I.P. with 3" brass cap stamped "T3N R9W S20 S21 S28 S29 2000 LS 849"; from which said B.T.'s now bear as follows: the 18" hemlock (now 22") at N55°E 26.4 ft. bears N51°30'E 26.40 ft. to scribed face, the 18" spruce (now 22") at S44°W 9.6 ft. bears S45°44'W 9.60 ft. to scribed face, and the 12" hemlock (now a 16"stump) at N54°W 40.6 ft. bears N52°43W 40.60 ft. to scribed face. set flush with ground two 5/8" X 36" rebars with yellow plastic caps stamped "K FOESTE LS 849" which bear as follows: S06°56'18"E 24.67 ft. and N65°17'14"W 12.64 ft. A steel spike GPS control point bears N51°46'08"W 71.11 ft. I set a 6' steel fence post with yellow location poster two feet south of corner. Corner is located on south side of large hemlock root wad. Basis of bearings is true bearings at longitude 123°48'11.05" West as determined from GPS observations.

Date: 4/13/2000

Present: K. Foeste, A Hofmann

APR 21 2000

REGISTERED PROFESSIONAL AND SURVEYOR

> OREGON JULY 12, 1988

KARL F/FOESTE 0849

Renews 1/1/2002