## BAYSIDE SURVEYING

11765 HWY 101 South Tillamook, Oregon 97141

Terry L. Jones 503-842-5551 Fax 503-842-5552

June 4, 2001

## REWITNESS

"ARBITRATED" 1/4 CORNER COMMON TO SECTIONS 9 AND 10 TOWNSHIP 2 SOUTH, RANGE 8 WEST

HISTORY GLO - Reported LOST by Sheppard in 1947

Sheppard set scribed post and marked 2 bearing trees on boundary line agreement Map B-124.

GONE: Scribed post

FOUND: Both of Sheppard's bearing trees - see Map B-124

I set a 2 ¼" brass cap stamped "T2S R8W ¼ S9 S10 LS 2507 2001" on a 1" x 30" galvanized iron pipe, top flush with rock mound, on steep NE slope, 30 feet South of Small Creek, (N71° W 160 feet) from fork in small tributary creek off of Edwards Creek, from which: 42" dead cedar snag with burned out face bears South 39° West 25.7 feet (S 29° W 25.7') (I scribed "1/4 S9 BT" on new face on root crown below burnt out face); 48" fir snag with face scribed "AC ¼ S BT" bears North 89° East 84.5 feet (N 89° E 84.5'); 16" Alder tree bark scribed "1/4 S10 BT" bears North 68° East 12.1 feet; 5" Hemlock tree scribed "X BT" on low face bears South 20° East 84.9 feet; Steel fence post 5 feet South.

In the presence of Terry Jones and Joe Jensen

PROFESSIONAL LAND SURVEYOR

JULY 23, 1991
TERRY L. JONES
1507

