BAYSIDE SURVEYING

11765 HWY 101 South Tillamook, Oregon 97141

Terry L. Jones 503-842-5551 Fax 503-842-5552

April 2002

REWITNESS

4 CORNER COMMON TO SECTIONS 33 and 34
TOWNSHIP 2 SOUTH, RANGE 8 WEST

I found:

BLM brass cap on 1" iron post stamped "T2S R8W $\frac{1}{2}$ S33 S34 1956", in stone mound, on steep West slope, approximately 150' west of ridge running North-South, approximately 450' N10°W to top of Grindstone Mt. (See BLM field notes.)

From which:

12" Cedar with healed face bears N65°E 69 lks. (5" Cedar bears N65°E 69 lks. See BLM field notes.)

16" Fir with healed face bears N33°W 26 lks. (12" Fir bears S33°W(bad quadrant) 26 lks. See BLM field notes.)

I set:

An orange carsonite post 4' North

In the presence of Terry Jones, Dallas Esplin

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 25, 1991
TERRY L. JONES
2507

