BAYSIDE SURVEYING

11765 HWY 101 South Tillamook, Oregon 97141 Terry L. Jones 503-842-5551 Fax 503-842-5552

April 2002

REWITNESS

4 CORNER COMMON TO SECTIONS 35 and 34
TOWNSHIP 2 SOUTH, RANGE 8 WEST

I found:

OSBF brass cap on $1\frac{1}{2}$ " galvanized iron pipe stamped $\frac{1}{4}$ S34 S35 1952 2311" in stone mound with GLO stone with $\frac{1}{4}$ " on northeast side. (See Rewitness Book 2, Page 203.)

From which:

Both GLO BTs very rotten:

46" Cedar stump with scribing " $\frac{1}{4}$ S34 BT RE 2311" bears N72°W 26.5'. (N72°W 26.5'. See Rewitness Book 2, Page 203.)

68" fir stump with scribing " $\frac{1}{2}$ S35 BT" bears N88°E 59.5'. (N88°E 59.5'. See Rewitness Book 2, Page 203.)

Note: monument appears to be in an active slide area, approximately 240' North of the road, but there are no ties to this corner from other corners to compare with. I held the monument as best evidence of the original GLO position.

I set:

Set an orange carsonite post 4' North, and 2 New BTs as follows:

17" Douglas Fir scribed "4 S34 BT" bears N72°W 12.35' to brass nail & washer stamped "LS 2507" between the B & T;

14" Douglas Fir scribed " $\mbox{\em S35}$ BT" bears N33°E 33.07' to brass nail & washer stamped "LS 2507" between the B & T;

In the presence of Terry Jones, Dallas Esplin

DATE DATE

OCT 3 2003

OUR PLEYORS OFFICE

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Jew Jones
OREGON
JULY 25, 1991
TERRY L. JONES
2507