# BAYSIDE SURVEYING

11765 HWY 101 South Tillamook, Oregon 97141

Terry L. Jones 503-842-5551 Fax 503-842-5552

April 2002

#### REWITNESS

CLOSING TOWNSHIP CORNER COMMON TO SECTIONS 36, 31 & 6 (West end)

TOWNSHIP 2 and 3 SOUTH, RANGE 8 and 7 WEST

(Northwest corner of Township 3 South, Range 7 West)

#### I found:

OSBF brass cap on  $1\frac{1}{2}$ " galvanized iron post stamped "T2S S36 R8W T2S R7W S31 S6 CC T3S 1975 RS707" flush with ground. (See Rewitness Book 5, Page 343.)

### From which:

 $4^{\prime\prime}$  x  $4^{\prime\prime}$  white wood post bears Northwest 1'. (See Rewitness Book 5, Page 343.)

28" Fir with healed face bears S52½°W 8.3'. (10" Fir bears S52½°W 8.3'. See Rewitness Book 5, Page 343.)

26" Fir with healed face bears S6°E 156.7'. (14" Fir bears S6°E 156.7'. See Rewitness Book 5, Page 343.)

25" Fir with healed face bears N17½°E 183.3'. (12" Fir bears N17½°E 183.3'. See Rewitness Book 5, Page 343.)

## I Set:

An orange carsonite post 4' North

In the presence of Terry Jones, Dallas Esplin

PROFESSIONAL LAND SURVEYOR

> JULY 25, 1991 TERRY L. JONES 2507