## OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: The NW 1/4 SW1/4 of Section 29	TOWNSHIP 1 South	RANG	NGE 9 West	
COUNTY: Tillamook DATE: 07-07-06				
CORNER DESIGNATION: Centerline – Centerline monument at Alder			(Please check one)	
Lane and Williams Avenue.				Condition Report Only
				Not Found
		×	Renewed	
			Unrecorded	
				Surveyed In
			区	Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.:  Map A-6113 by W.E. Anderson established original position of centerline monument. Replaced with 10" monument case and brass cap by the Tillamook County Surveyor in 1987.				
Found Monument(s) and Accessories (Condition & Source):  The monument case at this position was paved over by road improvements made to Alder Lane. After removing the paving lift around the lid of the monument case, the monument was found to be in good condition and marked as shown on map A-6113.				
Monument Set (Procedures and Description): A decision was made to have the contractor fill the monument case with asphalt due to the increasing failure rate of the monument cases around the county. We referenced the existing monument at 0.87' South and 0.78' East. A 2" diameter Tillamook County brass disk, stamped as shown hereon, was then set at the road surface with the subsurface monument remaining intact and in position.			Sketch of Set Monument:	
Other new accessories set: No new accessories set.				
New Bearing Trees: No bearing trees set.				
Location & Comments:				
Firm / Agency Address: TILLAMOOK COUN	ITY SURVEYOR'S OFFICE		S	SURVEYOR'S SEAL
Party Chief: Joe Jensen, Surv Notes:	ey Supervisor			REGISTERED PROFESSIONAL LAND SURVEYOR
Witness: Danny R. McNutt, Tillamook County Surveyor			8	DANNY P. Mc Nutto  COREGON JULY 11, 2000  DANNY H. MCNUTT  49230



RENEWAL12-31- 2006