OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: NE SE 34 TOWNSHIP: I North RANGE: 10 West			
COUNTY: Tillamook			DATE: 7/12/200
CORNER DESIGNATION: Centerline - Centerline monumer	of at Fourth	1	(Please Check One)
Street and Main Street in the City of Bay City.	,, ac , ourdi		Condition Report Only
Gueet and Iviant Gueet as the Gity of Day Oity.			Not Found
		Х	Renewed
		É	Unrecorded
			Surveyed In
		X	Referenced Out
Previous Rewitnesses, Restorations, Surveys, etc.: Map B-1554 is the rewitness record for this monument.			
Found Monument(s) and Accessories(Condition & Source): Found 3" diameter Tillamook County Brass Cap in an 8" diameter monument case in concrete under approximately 2" of asphalt. The found monument is in good condition and is found to be as described on Tillamook County Survey map B-1554.			
Monument Set(Procedures & Description): The lid to the 8" diam	1	cetch	of Set Monument
monument case was removed and the case was filled with concrete and a 2" diameter Tillamook County Brass Disk was placed at road surface. The 3" diameter brass disk is intact and in position. The 2" brass disk is stamped as shown hereon.			COUNTY SURVEYOR 2006
Other New Accessories Set: No new accessories set. New Bearing Trees: No new bearing trees set.			
Location & Comments:	Surveyor's S	tamı	2
		P	REGISTERED PROFESSIONAL AND SURVEYOR
Firm/Agency: Tillamook County Surveyor] α	Da	mmy R Me Nut
Address: 201 Laurel Avenue, Tillamook, Oregon 97141			OREGON JULY 11, 2000 NNY R. MCNUTT 49230
Party Chief: Joe Jensen, Survey Supervisor		R	ENEWAL12-31- 2006
Notes: This monument was paved over during road construction and was reported to us by Bob Olsen.	Office Use Only		STOOK CO.
Witness(es): Danny R. McNutt, County Surveyor]		DATE