OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: The Southeast	TOWNSHIP 1 South	RANGE 8 West			
1/16 corner of Section 19 COUNTY: Tillamook	<u></u>	<u> </u>		DATE, AT AA AT	
out Marcola de Chillada i a companya de la companya		10		DATE: 07-12-07	
CORNER DESIGNATION: The Southeast 1/16 corner to Section Township 1 South, Range 8 West, W.M., Tillamook County, Oreg				(Please check one)	
Township I South, Range o West, W.W., Thathook County, Oregon		(1).		Condition Report Only	
				Restoration	
				Rewitness	
				Unrecorded	
				Reset	
				Referenced Out	
Previous Rewitnesses, Resto	orations and Surveys, etc.: Map B-	530, Tilla	amo	ok County Survey Records.	
bronze cap stamped as shown found monument. Found a 48" diameter Hemlock tree), located at record position	hereon. I placed 120 pounds of con tree with a rotten face with the botto s, see Map B-530. s snag, approximately 40' tall with sc	crete ins	ide a	gon State Board of Forestry 3" diameter a 12" diameter plastic cylinder around the e visible, (was a 45" diameter Hemlock , (was a 23" diameter Hemlock tree),	
Monument Set (Procedures a	and Description): Not Applicable.	7 5	keto	ch of Found Monument:	
Other new accessories set: Set a 72" Hat Section post with yellow			SE 1/16 PRE SE 1/1		
monument.					
SURV" and nail set between th "A 15" diameter Hemlock tree s between the 'B & T' which bear	e 'B & T' which bears South 53° Eas scribed "T1SR8WSE1/16S19BT" wit	st 15.1'. h a brass	s wa	BT" with a brass washer stamped "TC sher stamped "TC SURV" and nail set AG ATTACHED.	
Location & Comments: This of an existing road.	corner is located approximately 100'	South			
Firm / Agency Address: TILLAMOOK COUN	TY SURVEYOR'S OFFICE		S	SURVEYOR'S SEAL	
Party Chief: Joe Jensen, PLS	60067, Survey Supervisor	REGISTERED PROFESSIONAL			
Notes:		0		anny R. Me Nutt	
Witness: Danny R. McNutt, PL Surveyor	S 49230, Tillamook County	*	No.	OREGON JULY 11, 2000 DANNY R. MCNUTT 49230 RENEWAL12 - 31- 2 0 0 7	

