OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 36	TOWNSHIP 2 South	RANG	RANGE 10 West	
COUNTY: Tillamook			DATE: 01-23-09	
CORNER DESIGNATION: The South 1/4 Corner of Section 36, T.		2 S.,		(Please check one)
R. 10 W., W.M.				Condition Report Only
				Restoration
			183	Rewitness
				Unrecorded
				Reset
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: B.L.M Field Notes Volume: OR-R0053 Page: 0124 (G.L.O. 2S10 Page 6, 1857), A-165 (1918), Book 4 Page 462 (1922), Book 2 Page 463 (1961), Book 6 Page 5 (1976), B-738 (1976), Rewitness #472 (1986), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found 3" brass cap, in cement, up 0.4', in good condition. The monument is stamped as shown hereon. (Book 4, Page 46) – Found 90" dia. Fir Stump, 7' tall, no marks visible, at record position (N 65° W 29.0'). (Book 2, Page 463) – Found stump remains of a Hemlock, 2.5' tall, scrib. partially visible, at record position (N 23° W 6.0'). (Book 6, Page 5) – Found rotten remains of a Hemlock, at record position (N 48° E 30.0'). (Rewitness #472) – Found hat section post, at record position (North 1.5').				
Monument Set (Procedures a	nd Description): Not Applicable.		Sketc	ch of Found Monument:
				S36 1/4 — o — LS 793 1986
Other new accessories set: Re-tagged the hat section post 1.5' North of monument.				
New Bearing Trees: * 13" dia. Hemlock bears N 29° W 9.6', scribed, "T2S R10W 1/4 S36 BT", tagged and painted. * 11" dia. Fir bears N 87° E 4.1', scribed, "T2S R10W 1/4 S36 BT", tagged and painted. * Indicates yellow Tillamook County metal location tag attached. All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze between the B and T.				
Location & Comments: This conference of Yellow Fir mainline logging re	orner is located approximately 350' states and a draw.	South		
Firm / Agency Address: TILLAMOOK COUN				SURVEYOR'S SEAL
Party Chief: Joe Jensen, PLS (60067, Survey Supervisor		1	REGISTERED PROFESSIONAL
	S 49230, Tillamook County Surveyor 16723, Survey Technician		Joseph V. Jewen	
MATERIAL PROPERTY OF THE PARTY	y olay paorini ilay pia mailika arapanyanjah kaki kerekendenden dipulitik dipulakan menalakan pangan dipulak m	мерапуск _у (JANUARY 10, 2006 JOSEPH V. JENSEN 60067 RENEWAL DATE: 08-30-09



G:\completed restorations\T2SR10WSouthquarterSec36.doc

472