OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: The NW ¼ SW¼ of Section 29	TOWNSHIP 1 South	RANGE 9 West		
COUNTY: Tillamook			DATE: 09-01-09	
CORNER DESIGNATION: Centerline - Centerline monument at Alder			T	(Please check one)
Lane and Williams Avenue.				Condition Report Only
				Searched for, not found
		X	Reset at surface	
			Unrecorded	
				Surveyed In
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: Map A-6113 by W.E. Anderson established original position of centerline monument. Replaced with 10" monument case and brass cap by the Tillamook County Surveyor in 1987. See Rewitness Book 7, Page 404 for monument reset and rewitness information done in 2006.				
Found Monument(s) and Accessories (Condition & Source): The 2" diameter brass disk set in 2006 was gone. We found the subsurface monument and then filled the old monument case with concrete and then reset the surface monument using the record reference information from Rewitness Book 7, Page 404.				
Monument Set (Procedures a	and Description): We referenced the	e	Sketch of Set Monument:	
reset monument at the record distances of 0.87 South and 0.78 East. A 2" diameter Tillamook County brass disk, stamped as shown hereon was then reset at the road surface, encased in concrete with the subsurface monument remaining intact and in position.			,,,,	
Other new accessories set: No new accessories set.				
New Bearing Trees: No bearing trees set.				
	s: See corner designation above.	,		
Firm / Agency Address: TILLAMOOK COUN	TY SURVEYOR'S OFFICE		9	SURVEYOR'S SEAL
Party Chief: Joe Jensen, P.L.S	5. 60067, Survey Supervisor			REGISTERED PROFESSIONAL LAND SURVEYOR
Notes:			-	Gaseph V. Gensen OREGON
Witness: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor			JANUARY 10, 2006 JOSEPH V. JENSEN	
Michael R. Rice, L.S. I. 16723	, Survey Technician		No.	60067 RENEWAL DATE: 06-30-2011

