OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 29	TOWNSHIP 2 South	RANGE 8 West		
COUNTY: Tillamook DATE: 1-08-10				
CORNER DESIGNATION: The Center North 1/16 Corner of Section 29, T. 2				
S., R. 8 W., W.M.	enter North 1/16 Comer of Section 28	7, 1. 2	×	(Please check one)
., r. o, r				Condition Report Only Restoration
				Rewitness
				Unrecorded
		1		
			무	Reset at surface
Design Design		4004)		Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: Map B-497 (1964), Map A-5266 (1985), Map A-7759 (2002), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" O.S.B.F. Brass Cap, good condition, down 0.7", on				
the top edge of a steep slope with a steel post in each quadrant at record position per Map A-7759. The monument was set in				
Map B-497 (1964). The monument is stamped as shown hereon. (Map B-497) – Found 30" dia. rotten Noble Fir Stump, (was 30"), 5' tall, bears (S 59° W 15.7'), no marks visible.				
(Map B-497) – Found 36° dia. Fir Stump, (was 26°), 5' tall, bears (N 31 1/2° E 28.2'), no marks visible.				
(Map B-497) – Found white painted cedar post, bottom rotten, lying next to monument, (S.W. 1.0').				
(Map A-7759) – Found (11" dia. Hemlock bears N 89° W 5.90' to brass nail and washer), scribing visible.				
(Map A-7759) – Found (13" dia. Hemlock bears N 28° E 10.25' to brass nail and washer), with tag and scribing visible.				
() Indicates record information, Tillamook County Survey Records.				
Monument Set (Procedures and I	Description): Not applicable.	Sketch (of F	ound Monument:
				ATE BOARD OF
			,	1/16
	İ		/5	
			(2	(CN1/16 • 529)
			'	
				1964
				13 40 1
	i			
New accessories set: Set 120 lbs. of concrete in a 12" dia. cylinder around monument. Set 72" hat section post with a yellow				
metal location tag, 3.3' North from monument.				
New Bearing Trees set: N/A				
				<u></u>
	ument is approx. 250' North of Simm			
Ridge Logging Road, on the top of	a steep slope overlooking Skookum l	Lake.		
Firm / Agency				SURVEYOR'S SEAL
Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE				
201 Laurel Avenue				
Tillamook, Oregon 971	41			
D. (Oliver land)			-	DECIOTECT
Party Chief: Joe Jensen, P.L.S. 60	067, Survey Supervisor			REGISTERED PROFESSIONAL
Notes: Digital images were taken of the found bearing trees and terrain.			1	LAND SURVEYOR
Digital images were taken of the lound bearing trees and terrain.				The source of
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor			1	Gaseph V. Chorne
•	. 16723, Survey Technician	. ,		OPECON
				OREGON JANUARY 10, 2008
				JOSEPH V. JENSEN
				60067
				RENEWAL DATE: 06-30-2 014

