OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 36	TOWNSHIP 3 South	RANGE 10 West		
COUNTY: Tillamook		<u> </u>	DATE: 9-22-09	
CORNER DESIGNATION: The South 1/16 Corner common to Sections 35			(Please check one)	
and 36, T.3S., R.10W., W.M.		. 0	Condition Report Only	
, , ,				
		×	Rewitness	
			Unrecorded	
			Reset at surface	
			Referenced Out	
Previous Rewitnesses, Restorations and Surveys, etc: Map B-505 (1965), Map B-1046 (1982), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3" dia. O.S.B.F. Brass Cap, good condition and flush. Found cap was pointing N 20° W. The monument was set on Map B-505 (1965). The monument is stamped as shown hereon. Found 1" X 47" Iron Pipe, and a rotten white painted cedar post, lying next to the monument. Found fence post with yellow metal location tag North 2.5' from the monument. Found carsonite post S 86° E 3.0' from the monument. (Map B-505) — Found rotten Fir Stump (was 21" dia.), 3' tall, bearing (S 89° E 26.4'), with tag and scribing "T" visible. (Map B-505) — Found rotten Fir Stump (was 23" dia.), 1' tall, bearing (N 53° W 37.2'), with tag affixed. (L. Whitmore 1976) — Found rotten Fir Stump (was 24" dia.), 6' tall, bearing (S 48° W 16.9'), scribing visible.				
Monument Set (Procedures and		Sketch of I	Found Monument:	
		S 1/16 S35 S36 1965 65 701		
New accessories set: Rotated cap North and set 120 lbs. of concrete around monument.				
New Bearing Trees set: *16" dia. Douglas Fir bears S 2° E 10.8' to face, scribed, tagged and painted. *16" dia. Douglas Fir bears S 84° W 53.6' to face, scribed, tagged and painted. * Indicates an aluminum nail w/ washer marked "Till. Co. Surveyor" on the face between the scribed "B" and "T".				
Location & Comments: N/A				
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141			SURVEYOR'S SEAL REGISTERED	
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor			PROFESSIONAL LAND SURVEYOR	
Notes: Digital images were taken of the monument, the found bearing trees and the new accessories.		ailily	Joseph V. Grusen	
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician		yor	OREGON JANUARY 10, 2008 JOSEPH V. JENSEN 60067	
			RENEWAL DATE: 08-30- 2011	

