OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: SE Corner of 10	TOWNSHIP 4 South	RANGE 7 West		
COUNTY: Tillamook DATE: 8-8-11				
CORNER DESIGNATION: The Section Corner common to Sections 10, 1			(Please check one)	
14 and 15 T. 4 S., R. 7 W., W.M.	·	-, , 	Œ	Condition Report Only
		Ī		Restoration
		Ī		Rewitness
		Į		Unrecorded
		į		Reset at surface
				Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0118 Page 782, (GLO Book 4S7 Page 6) (1873), Rewitness Book 3 Page 67 - 68 (1961), Map A-1614 (1968), Map B-590 (1969), Tillamook County Survey Records.				
Found Monument(s) and Accessories (Condition & Source): Found a 3 "dia. BLM Brass cap, set in Book 3, Page 67-68 (1961), marked as shown hereon. Found the original stone, broken, along side of the monument in the rock collar. (Book 3, Page 68) — Found 40" Fir (was 20") (bears N 39 1/2° E 130 lks. [85.80']) face healed with a yellow metal location tag. (Book 3, Page 68) — Found 34" Fir Stump (was 10"), 2' tall, (bears S 20° E 119 lks. [78.59']) no markings visible. (Book 3, Page 68) — Found 42" Fir (was 16") (bears S 82° W 115 lks. [75.90']) healed face with a yellow metal location tag. (Book 3, Page 68) — Found 36" Fir Stump (was 25"), 6' tall, (bears N 71° W 147 lks. [97.02']) healed face and yellow metal tag. () Indicates record information, Tillamook County Survey Records.				
Monument Set (Procedures and I	Description):	Sketch (of F	ound Monument:
			SID SII SID SII SID SII SID SIA SIA SIA SIA SIA SIA SIA SIA	
New Accessories set: Set 120 lbs. of concrete in a 12" diameter cylinder around found monument. Set 72" hat section post North 3.0' from monument.				
New Bearing Trees Marked: N/A				
Location & Comments: Monument is located approx. 200' North of Bald Mountain Road.		ald		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tiliamook, Oregon 97141			SURVEYOR'S SEAL	
Party Chief: Joe Jensen, P.L.S. 60067, Deputy County Surveyor				REGISTERED
Notes: Digital images were taken of the monument and its accessories. Accessories were tied with a Topcon GPT 3005 Total Station.				PROFESSIONAL LAND SURVEYOR
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician				Jaseph V. Gensen
	осни дравно це, поче си настипни стенице на веройни восточе в почес и объекветнице до восноје две образоване до		ec)	JANUARY 10, 2008 JOSEPH V. JENSEN 60067 RENEWAL DATE: 06-30- 2 0 13

