## OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT Tillamook County Surveyor's Office

SECTION: 3	TOWNSHIP: 3N	RANGE: 9W	RANGE: 9W		
COUNTY: TI			<b>DATE:</b> 10/24/2012		
CORNER DES	BIGNATION:		(Please Check One)		
CENTER-NOR			Condition Report Only		
CHNIER-NOR	/ -V		Restoration		
		Γ	x Rewitness		
ĺ			Not Found		
ĺ			Reset		
			Referenced Out		
Previous Rewitnesses, Restorations, Surveys, etc.:  ESTABLISHED BY COUNTY SURVEY NUMBER A-2663, SET AN OREGON STATE BOARD OF FORESTRY 3/4" PIPE AND  CAP; 18" FIR N4°W 62.6'; 16" FIR S66 1/4°E 44.4' (RS707) YMLP					
	*				
	ment(s) and Accessories(Condition & Source): ASS DISK ON 3/4" GALVANIZED IRON PIPE, AS SHOWN				
FOUND 18" FI FOUND 16" FI	IR N4°W 62.6', NOW 31" WITH HEALED SCRIBE SCAR.  IR S66 1/4°E 44.4', NOW 25" AND 7' TALL DECAYING  PDATED WITH PAINT AND YMLP.	UPDATED WITH			
Monument Se	et(Procedures & Description):	Ske	tch of Cap		
			53		
New Bearing					
Location & Co	FIR SCRIBED "CN 1/16 S3 BT" WITH A YMLP; CENTER	Surveyor's Sta			
			REGISTERED PROFESSIONAL AND SURVEYOR		
Firm/Agency:	AKS ENGINEERING & FORESTRY, LLC	1/	1 / 1 1		
	13910 SW GALBREATH DR, SUITE 100	//	uM ICK. To		
Address:	SHERWOOD, OR 97140	<i>(V)</i>	- iv-yw		
	(503) 925-8799		OREGON JANUARY 9, 2007		
Party Chief:	ROBERT BIALOBRZEWSKI & JIMMY COOK		NICK WHITE 70652LS RENEWS: 6/30/14		
Notes: AKS J	OB NUMBER 3145	Office Use Only			
	= YELLOW METAL LOCATION POSTER	ĺ			
L			(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)		
Witness(es):			OCT 31 2012		
<u> </u>		I	1 001 0 . 101-		

800X 8 014