## WEYERHAEUSER GOVT. CORNER VISITATION

OU.	SECTION 36 TOWNSHIP 2S RANGE 7W W.M. BLM ID# 540200	
	DLC CORNER NORTH QUARTER	
W.Course	DATE 8/04/16 X_CONDITION REPORTRENEWED	
	PREVIOUS RENEWALS/SURVEYS, ETC.: B-3087	
	MONUMENT (S) AND ACCESSORIES FOUND, CONDITION AND (ORIGIN)	
	2 3/8" BRASS CAP, ON A 1 1/4" IRON PIPE, UP 2". FOUND A 3/4" FIBERGLASS POST 1' NORTH OF MONUMENT	(B-3087)
	14" D.FIR, WITH A HEALED FACE AND W.I.I. B.T. TAG, BEARS S32 1/2°E, 26.4' (12" DOUGLAS FIR, BEARS N32°30'E, 26.35' - B-3087)	(B-3 <mark>087)</mark>
	19" D.FIR, WITH A HEALED FACE AND W.W.I. B.T. TAG, BEARS S28 W, 58.9 (16 1/2" DOUGLAS FIR, BEARS S28 W, 58.90' - B-3087)	(B-3087)
	19" D.FIR, WITH A HEALED FACE AND W.W.I. B.T. TAG, BEARS N74°W, 29.7' (13 1/2" DOUGLAS FIR, BEARS N74°W, 29.70' - B-3087)	(B- <mark>3</mark> 087)
	14" D.FIR SNAG, WITH A HEALED FACE AND W.W.I. B.T. TAG, BEARS N4°W, 34.0' (14" DOUGLAS FIR, BEARS N04°W, 34.00' - B-3087)	(B-3087)
	MONUMENT (S) SET (PROCEDURES AND DESCRIPTION)	

NONE

## **NEW ACCESSORIES:**

NONE


## COMMENTS:

ALL FACES WERE PAINTED BLUE, AS WAS A 6" BAND AROUND THE TREES.

DISTANCES TO THE BEARING TREES WERE MEASURED WITH A 75' BUCKERS TAPE TO AN EXISTING NAIL AT THE SIDE CENTER.

BEARINGS WERE COMPARED WITH A HAND COMPASS WITH THE DECLINATION SET AT 16 °E.

## MONUMENT DETAIL:



INMAN SURVEYING, LLC 1148 LISA CT NE KEIZER, OR 97303 (541)521-8311

