OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT Tillamook County Surveyor's Office


SECTION:	5, 6, 7, 8	TOWNSHIP:	18	RANGE:		7W		
COUNTY:						DATE:	JUNE 21, 2016	
CORNER DESIGNATION:					(Please Check One)			
SECTION CORNER COMMON TO SECTIONS 5, 6, 7, AND 8, T1S, R7W					Condition Report Only			
					7 10	Restoration		
					X	X Rewitness		
						Not Found		
						Reset		
					13	Reference	d Out	

Previous Rewitnesses, Restorations, Surveys, etc.:

Found Monument(s) and Accessories(Condition & Source):

FOUND OREGON STATE BOARD OF FORESTRY BRASS CAP, STAMPED "T1S R7W S6 S5 S7 S8 1954 PE 2311", ON 1 1/2" IRON PIPE, IN STONE MOUND, FLUSH, FROM WHICH: 67" ROTTON FIR STUMP WITH SCRIBING VISABLE BEARS N 30 1/2° W 108.7'; 78" ROTTING TWIN FIR SNAG, \pm 75' TALL, SCRIBING VISABLE, BEARS N 47° E 200'; 30" x 30" x 40" STONE, SCRIBED "BO" WITH CARSONITE POST 2' SE, BEARS S 48° E 31.8'; WHITE 4"X4" POST BEARS NE 1.5'. SEE REWITNESS BOOK 1, PAGE 102.

Monument Set(Procedures & Description):



Other New Accessories Set:

CARSONITE POST 2" NORTH

New Bearing Trees:

SET 5/8" x 40" REBAR WITH PLASTIC CAP MARKED "TERRY JONES LS 2507" WITH WHITE POST 1' NE, ON TOP OF RIDGE, BEARS N 20° E 22.11'; SET 5/8" x 40" REBAR WITH PLASTIC CAP MARKED "TERRY JONES LS 2507" IN CENTER LINE OF OLD CAT ROAD WITH CARSONITE POST 1' NW, BEARS N 67° W 58.73'; 14" SPRUCE SCRIBED "S7 BT" ON LOW BLAZE, BEARS S 36° W 55.33' TO BRASS NAIL AND WASHER "LS 2507" BETWEEN B&T; 30" TWIN DOUG FIR, SCRIBED "T1S R7W S8 BT" BEARS S 71° E 10.70' TO BRASS NAIL AND WASHER "LS 2507" BETWEEN B & T.

Location & Comments:

MONUMENT IS ON SOUTHWEST EDGE OF FLAT, 600' NORTH OF TOP RIDGE.

The state of

Firm/Agency:

BAYSIDE SURVEYING

Address:

11765 HWY 101 SOUTH TILLAMOOK, OR 97141

Party Chief:

TERRY JONES

Notes:

FILE NAME rewitness\T1S-R7W-S5-6-7-8.xls

Witness(es):

TLJ/DWE

Surveyor's Stamp



RENEWAL DATE 6-30-17

