## OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT Tillamook County Surveyor's Office

SECTION:	9	TOWNSHIP:	18	RANGE:		8W
COUNTY:		TILLAMOOK				<b>DATE:</b> 9-Feb-18
CORNER DESIGNA	TION:	CS 1/16	•		1	(Please Check One)
	<del>-</del>					Condition Report Only
						Restoration
						Rewitness
						Not Found
						Reset
<b>D</b> . <b>D</b>						Referenced Out
Previous Rewitness						
MONUMENT SET C	N MAP B-245	)				
Found Monument/s	s) and Acces	ories(Condition & Sc	urco):			
				S CAP ON 1.1	/2" X 4	40" GALVANIZED IRON PIPE,
		LS 2507 2001", IN GC				
Monument Set(Pro			THEN BUG	]		
		IEW ACCESSORIES				
		OGGING ROAD WOI ROM THE NEW ACC		RUART 9,		
		GRADE ON LANDIN		CULVERT		
WHICH PROTRUDE			O MOIDE 10	OOLVLIKI		
				ľ		
]						
New Bearing Trees:		TREES SOME				
NONE SUTABLE, C	ILD BEARING	I REES GUNE				
			•			
Other New Accesso	rie					
		WITH PLASTIC CAP	MARKED "TE	RRY JONES	LS 250	07" (RBPC) SOUTH 21°32'20"
						583.52'; RBPC IN CL GRAVEL
•						ESAT EDGE OF ROAD
SOUTH 18°55'28" W	/EST 338.14'; 8	0 D SPIKE IN TOP O	F 36" FIR ST	JMP ALONG E	ESAT	EDGE OF ROAD SOUTH
						OF ROAD SOUTH 24°21'43"
				TH STEEL PO	ST 1'	EAST SOUTH 88°32'04" EAST
31.07'; CARSONITE	POST EAST 3	'; STEEL POST SOU	TH 3'			
1						
Location & Comme	nts:			Surveyor's S	tamp	
				REG	SISTER	RED
				PROF	i.	
				LAND	_	
Firm/Agency:				<b>6</b>	Λ	7
BAYSIDE SURVEYIN	NG ·			Jenn/		(Lornar )
Address:				7	DREGOR	7013
11765 HWY 101 SOI				I JUL	.Y 25, 19	961
TILLAMOOK, OR 97	141			TERRY	/ L. J( 2507	ONES
Party Chief:				Water Comments		
TLJ				5515144		
Notes					LDAI	TE 6-30-19
Notes: REWITNESS\T1S-R	0W 50 CS1 16	· vla		Office Use Only		
KEANLINEOO(I 19-K	044-99-091-10	.XIS				
Witness(es):				مي	-	
DWE				). "		* <b>6</b> 0}
KJJ				/~ <i>/</i> *		
				l vy		The state of the s
					- N 1-	2 2/1/2 E
				i the	<u> </u>	
				S. C.		
					<u> E</u> YGR	s Sir
				New York	والمراجع والمراجع المراجع	4 Winds