CORNER INVESTIGATION REPORT

FS INDEX ID: M-19

CENTER-SOUTH 1/16 GCDB ID: 540420 CORNER:

DATE: 5/11/2018

HISTORY OF VISITATIONS:

TOWNSHIP: 3S

STATE:

OREGON

(1)1982 - L.D. BISHOP, CSF# B-1085

RANGE:

10W

COUNTY: TILLAMOOK

FOREST: SIUSLAW

14 **SECTION:**

MERIDIAN: WILLAMETTE NFSL PROPERTY BOUNDARY CORNER?:

DISTRICT: HEBO

LINE(S) POSTED: NORTH - 1982

MAINTAINED:

EAST - 1982

GUARD POST(S):

NORTH - 2017

EAST - 2017

CORNER HISTORY:

(1) ESTABLISHED CORNER, SET ALUMINUM PIPE/CAP & 2 BT'S.

REGISTERED PROFESSIONAL LAND SURVEYOR

onthan Bil reut OREGON JONATHAN B. DREW II

89396 EXPIRES: 12/31/2019 RECORD MEASUREMENTS:

RECORD CORNER ACCESSORIES: A LARGE ROOT HOLE, DOWNED HEMLOCK LAYS EAST.

(1)N24°W - 12.5 FT

A LARGE ROOT HOLE, DOWNED HEMLOCK LAYS EAST OVER CORNER POSITON. (1)S36°W - 4.1 FT

POSITION. BEARING TREE LOG COULD NOT BE SAFELY CUT OUT & SOIL/SLOPE CONDITIONS ARE SUCH THAT THE POSITION CAN NO LONGER SUPPORT A

MONUMENT FOUND/SET;
MONUMENT FALLS UNDER DOWNED BEARING TREE & IS LIKELY OUT OF

STABLE MONUMENT. PLAN TO SET WC OR RM'S IN WINTER 2018-2019.

NEW CORNER ACCESSORIES:

NO NEW ACCESSOIRES ESTABLISHED, FUTURE RE-ESTABLISHEMENT PLANNED

SEE OTHER INFO SECTION BELOW.

METHOD OF MEASUREMENT:

NO NEW MEASUREMENTS TAKEN,

FILED AS CONDITION REPORT.

CORNER MAINTENANCE/OTHER INFO:

CORNER NOTED AS NEEDING TO BE RE-MONUMENTED OR REFERENCED OUT & NEW ACCESSORIES ARE ALSO NEEDED. THIS WORK IS PLANNED FOR WINTER 2018-2019 & WILL BE DONE BY RETRACEMENT OF THE SOUTH HALF OF THE NORTH-SOUTH CENTERLINE OF SECTION 14 & A RECORD OF SURVEY & CORNER REPORT WILL BE FILED IF/WHEN THAT WORK IS COMPLETED. NFSL LINES BEAR: (1)N0°31'24"E - 1376.29 FT & (1)S86°38'35"E - 2687.35 FT

GEODETIC COORDINATES:

DOCUMENTS ON FILE AT:

LATITUDE: N 45° 18' 23.517" LONGITUDE: W 123° 52' 26.278"

WILLAMETTE NATIONAL FOREST 3106 PIERCE PARKWAY, STE D SPRINGFIELD, OREGON 97477

ELLIPSOID HEIGHT:

DATUM: WGS84

SOURCE: USGS QUAD MAP, FOR NAVIGATION TO CORNER.

DATE OF INVESTIGATION: 12/06/2017

REPORT BY: JONATHAN B. DREW II, PLS#89396, CFedS#1664

FIELD CREW: JACOB HUNT, USFS SURVEY TECH.

KYRK BARRON, USFS FIRE F.E.O.

CAP DIAGRAM:

MONUMENT NOT RECOVERED, FALLS UNDER DOWNED BEARING TREE.

THIS DOCUMENT FILED IN CS OFFICE: YES OTHER DOCUMENT FILED WITH CS: NONE